



False Trips, Production Downtime, How Much is it Costing You?


Did you know that “false or nuisance trips” can be a result of poorly aligned safety light curtains? Incorrect alignment in all 3 axis can cause dust or moisture in the environment to decrease the beam signal just enough to cause a short trip – stopping your process and costing you money from production downtime.

TR Electronic Lightbarrier features on board status LEDs that help you ensure all optics are perfectly aligned during setup. Proper alignment the first time can save costly downtime from nuisance trips in the future.



Additional Features:

- All functions can be set on the unit using dip switches – including cascading, blanking and muting. No need to pull a laptop to the factory floor to set up a light curtain.
- Standard M12 connectors on all cabling
- Available in finger, hand, or body protection, and available in 6 inch increments for proper sizing.



Demo Program:

Contact us today to see if you qualify for a free product demo.

Application Assistance:

Toll-Free: 1 (800) 265-9483 | E-mail: customer@trelectronic.com

About TR Electronic:

For over 20 years TR Electronic North America has been providing solutions for a wide variety of industries. TR Electronic is committed to providing the best possible service and support to its customers. Therefore, to always ensure you have the help when you need it, TR Electronic offers a complimentary online support center, 24/7 technical support, installation and commissioning assistance, network/bus analysis and technical services training.